



ANDERSON ENGINEERING AND SURVEYING, INC.

PROFESSIONAL ENGINEERS AND LAND SURVEYORS

17681 Hwy 395, Lakeview, Oregon 97630
(541) 947-4407 Fax (541) 947-2321

www.andersonengineering.com

PROJECT INSPECTION REPORT

PROJECT NAME: Crescent Wastewater Treatment Facility

DATE AND TIME: 8/7/19 12:00 PM

WEATHER: 80s Sunny

TRADES ON JOB: N/A

LOCATION: Site of the Wastewater Treatment Facility

COMMENTS: Darryl Anderson and myself conducted a “Punch through” inspection with the contractor; a “punch through” inspection is like a final draft. The treatment facility is 98% complete. All fencing is completed. Gates are in place, less a single location. Liner is complete. All roads are graveled. All plumbing, air release, valves, switches, etc are complete. Other than minor details such as putting up a panel mount for monitoring equipment, staff gauge installations, etc. the only major thing that remains is installing irrigation handlines and sprinkler heads.



Figure 1: Looking south at the irrigation fields on/off valves to direct recycled waters to either irrigation field if needed in the future.

INSPECTOR: Nicole Braudy

COPIES TO: Crescent Sanitary District, Bob's Excavation