



ANDERSON ENGINEERING AND SURVEYING, INC.

PROFESSIONAL ENGINEERS AND LAND SURVEYORS

17681 Hwy 395, Lakeview, Oregon 97630

(541) 947-4407 Fax (541) 947-2321

www.andersonengineering.com

PROJECT INSPECTION REPORT

PROJECT NAME: Collection System – Crescent OR Sewer System

DATE AND TIME: 4/2/20

WEATHER: Sunny, 30s

TRADES ON JOB: Morello Construction

LOCATION: Crescent, OR

COMMENTS: Work continues on the south Main st crew. With a final manhole and approximately 300' of mainline, the south Main st crew has completed that run and will remobilize to start work along Bonner Lane on Monday. The north Main st crew is still hammering away at bedrock, laying approximately 60' of mainline today. Service connections along Bonner and Ward was staked today.



Figure 1: Image of a mainline trenchwork along the south Main st line.



Figure 2: Image of the jack-hammering completed along the North Main St line, not the piles of removed broken bedrock on the left of the picture. This will be removed once work is completed and clean-up operations occur.

INSPECTOR: Nicole Braudy

COPIES TO: Crescent Sanitary District, Klamath County, Morello Construction